

STONHARD® | SPOTLIGHT

STONHARD PROVIDES ULTRA-DURABLE, HYGIENIC FLOOR AND WALL SOLUTIONS FOR PHARMACEUTICAL COMPANY



Problem: Renovation caused imperfections in concrete and customer needed a hygienic solution at the walls

Product Solution: Stonshield® HRI with Stonkote® CA7 and Polysto® OP20F

Scope of work: Fill suite and support rooms

Stonhard knows that pharmaceutical spaces require high-performing, innovative solutions to keep their operations running smoothly and safely. When a global pharmaceutical company was making renovations on their Texas facility's fill suite and support rooms, they came to Stonhard to solve their problems and ensure an effective, long-term solution. During the renovation of the fill suite, all the walls were removed, and patching was required where the walls once stood. Stonhard applied a quarter inch mortar base to level out imperfections in the concrete and the different elevations between old rooms and walls. Stonshield® HRI was chosen by the customer for its decorative quartz aggregate, durability, and chemical and stain resistance.

In addition to a flooring system, the customer was looking for an alternative to the stainless-steel bumper rails they had used to protect walls from damage by carts. Cleaning behind these rails was difficult. Stonhard, the exclusive turnkey partner of Polysto® in the United States, installed OP20F, a prefabricated, exceptionally durable, water-resistant curb system that provides sanitary design, a seamless transition from floor to wall, and a system that is much easier to clean.